

InfoTech

• N E W S F R O M P H T E C H •

Infotech5852_53_56A 09-04-16
Page 1 out of 2
BULLETIN NO.: 116

R & D TECHNICAL BULLETIN

Product Improvement

PART NUMBER: 5852, 5853 and 5856.

05852.05.00.4880 / 05852.07.00.4880 / 05852.08.33.4880

05853.05.00.4880 / 05853.07.00.4880 / 05853.08.33.4880

05856.05.00.4880 / 05856.07.00.4880 / 05856.08.00.4880

DESCRIPTION: Inside frame extensions

PRODUCT IMPROVEMENT EXPLANATION:

In order to facilitate the assembly between each other and into the frames. We have modified their hooks so that they grip onto one side only. An additional retaining leg has been added to improve the look of the joint between two pieces. The surface finish is much more rectilinear and improved than before. *(Please refer to the drawings on the following page for explanation.)*

Compatibility:

The present profiles can't be assembled with the new ones due to aesthetics. Although, it is still feasible to do so if the aesthetic quality is not required.

PRODUCT OFFER:




Please note that this new improved part will be available gradually as we run out of our present inventory. If you have any further questions, please contact our customer service department or technical support.



8650, boulevard de la Rive-Sud
Lévis (Québec) G6V 9G9
T 418.833.3231 F 418.835.1145
www.phtech.ca

to be continued on page 2




Actual version of the inside frame extensions:



Actual version :

Illustration of the inside frame extensions. The hook is shaped as an arrow with legs.

New version of the inside trims:



Improved version :

Illustration of the inside frame extensions. The hook is now identical to the one on the brick moulds.

Photo of the No. 5856 (improved part):

Photo of the No.5853 frame extension. The part is now straighter and the finish is improved.

